

HISTORIC AMERICAN ENGINEERING RECORD

HAER  
CONN,  
1-DA,  
2-

Index to Photographs

**Patch Street Bridge**

HAER No. CT-30

Spanning Kohanza Brook on Patch Street  
Danbury  
Fairfield County  
Connecticut

NOTE: Photographs 1-7, 20 were taken by Gerald Weinstein, photographer, on December 9, 1985. Photographs 8-19 were taken by Gerald Weinstein on March 3-6, 1986

- CT-30-1      VIEW OF SOUTH ELEVATION
- CT-30-2      VIEW OF NORTH ELEVATION
- CT-30-3      VIEW OF ROAD SURFACE AND SOUTH FACE, LOOKING EAST
- CT-30-4      VIEW OF ROAD SURFACE AND NORTH FACE, LOOKING WEST
- CT-30-5      VIEW OF EAST ARCH UNDERSIDE, LOOKING EAST
- CT-30-6      VIEW OF WEST ARCH UNDERSIDE AND SOUTH FACE VOUSSOIRS, LOOKING  
NORTHWEST
- CT-30-7      DETAIL VIEW OF DRAIN (ABOVE) AND BRICK SEWER OPENINGS IN SOUTHWEST  
ARCH UNDERSIDE, LOOKING WEST
- CT-30-8      DETAIL VIEW OF DRAIN OPENING IN NORTHWEST ARCH UNDERSIDE, LOOKING  
WEST
- CT-30-9      VIEW OF ARCH SECTION EXPOSED DURING DEMOLITION, LOOKING EAST
- CT-30-10     DETAIL VIEW OF SECTION OF ARCH, NORTHEAST SPANDREL AND APPROACH  
WALL, AND RUBBLE/FILL EXPOSED DURING DEMOLITION, LOOKING EAST
- CT-30-11     VIEW OF UPPER ARCH SURFACE, NORTHWEST DRAIN OPENING, AND RUBBLE  
BACKING OF NORTH SPANDREL EXPOSED DURING DEMOLITION, LOOKING  
NORTHEAST
- CT-30-12     VIEW OF NORTHWEST APPROACH WALL AND RETAINING WALL (RIGHT) EXPOSED  
DURING DEMOLITION, LOOKING SOUTH
- CT-30-13     DETAIL VIEW OF TOP OF NORTHEAST DRAIN, LOOKING NORTHWEST
- CT-30-14     DETAIL VIEW OF LOWER CHANNEL OF CENTRAL EAST DRAIN, LOOKING WEST

Patch Street Bridge  
HAER No. CT-30  
Index to Photographs  
(Page 2)

CT-30-15    DETAIL VIEW OF CERAMIC DRAINPIPE, CENTRAL WEST DRAIN, LOOKING EAST

CT-30-16    DETAIL VIEW OF TOP OF BRICK SEWER, LOOKING EAST

CT-30-17    DETAIL VIEW OF SECTION OF BRICK SEWER, LOOKING WEST

CT-30-18    DETAIL VIEW OF TIMBER FOUNDATION FOOTINGS, LOOKING EAST

CT-30-19    DETAIL VIEW OF THE SOUTHWESTERNMOST ARCH FOUNDATION STONE, WITH  
MORTAR FRAGMENT, LOOKING NORTH

CT-30-20    DETAIL VIEW OF IRON-BANDED WOOD PIPE UNDER NORTHWEST ARCH CORNER,  
LOOKING NORTHWEST